

Lesson learned in Tehran DPF retrofit project

Dec 2016, Inspection Workshop, Hossein Izanloo

DPF Potential Failures

- High level soot generation
- High rate of ash build-up in the filter
- Low performance regeneration or no regeneration
- DPF catalyst poisoning
- Substrate cracking or deformation
- Back pressure monitoring system problem
- Low efficiency cleaning



Main causes of high level soot

- Worn fuel injectors lead to excessive fueling
- Dirty air filter reduce air flow
- Low boost turbocharger do not produce sufficient air
- Low performance intercooler reduce air flow








Main causes of high level soot

- Vaporized coolant from head gasket leaks to cylinder
- Duty cycle of vehicle in real world is not compatible with duty cycle that DPF designed and adjusted for that





High rate ash - High rate lube oil consumption

- Original old engine designed with high level oil consumption
- Excess oil from worn piston rings, fuel injectors, valves, ..
- Oil leakage from Turbocharger
- High oil splashing in oil pan because of oil filling more than max level
- Low quality oil because of fuel mixing, high mileage, ..



High rate ash - High rate of FBC dosing

- Initial dosing adjustment is not correct
- □ Fuel tank level gage failed
- Electronic control unit failed







High rate ash - Oil quality and engine wear

- Using high ash lube oil
- □ High rate engine wear and exhaust component corrosion
- Adding clean or used oil to fuel tank





Low performance regeneration

- Looseness, fraying and corrosion of wiring and connectors of control system
- Lack of FBC in dosing tank because of leakage or not filling
- Fuel tank level gage failed which make dosing problem
- Duty cycle is low load, low speed with frequently stops at idle speed









Low performance regeneration


- □ Control unit stop regeneration to protect high voltage (battery or alternator problem)
- ECU, sensor or actuators failed
- Interaction made between ash and soot prevent oxidation progress
- DPF cleaning by steam water made






cement-like species from unremoved

Battery over voltage problem



Aged battery voltage



New battery voltage



DPF catalyst poisoning

- Frequently using high sulfur fuel
- Adding oil or additive to fuel tank
- Oil leakage from turbocharger to exhaust
- Coolant leakage from EGR system to exhaust
- Water cleaning, extra air pressure cleaning or extra heating in cleaning process



Substrate deformation, melting or cracking

- Oil leakage to DPF
- Fuel leakage to DPF
- Regeneration strategy failures against high soot rate, low FBC rate, high sulfur fuel and ..
- Failure in Heat-up and cool-down of cleaning process



Oil leakage from Turbo made crack



Fuel leakage from injector deformed DPF



Substrate deformation, melting or cracking

- Failure in Heat-up and cool-down of cleaning process
- Substrate dropping accident
- Hammering on mounting surface to remove ash during cleaning
- DPF vibration because of looser or missing fastener
- Leaving substrate near to welding services







Back pressure monitoring system

- Sensor failures
- Wiring and connectors loosening, corrosion,...
- Disconnecting, taping over or blocking displayer
- Misunderstanding the meaning of indicator lights





Low efficiency cleaning

- One type of cleaning machine and cleaning procedure may not be suitable for all DPF types
- Cleaning takes time
- Visual Inspection, weighting, flow measurement and endoscope inspection are necessary









